

Appendix J

Cumulative Statistics on Complaints, Notification of Summons and Successful Prosecutions

	Date received	Subject	Status	Total no. received in this month	Total no. received since project commencement
Environmental complaints (1)	29 September 2021 (Referred by the Contractor on 5 October 2021)	<p>Environmental Complaint No: EC-043-CKRKTW20211005_01_C085</p> <p><u>Details of Complaint</u></p> <p>A complaint referred from EPD (EPD ref.: K10/RE/00023313-21) was received by Gammon Construction Limited on 5 October 2021. The details of the complaint regarding water quality were described as follows:</p> <ul style="list-style-type: none"> - Date of Complaint received: 29 September 2021 - Complaint of polluting effluent discharged to the sea from construction site at the waterfront near Kowloon City Ferry Pier. - Please ensure the work fulfill the relevant environmental legislations and their subsidiary regulations. - Please take necessary environmental measures to minimize the environmental nuisance arising from the construction site. <p>A. Details of Investigation and findings:</p> <ul style="list-style-type: none"> - As reported by the Contractor, the construction activities conducted at Ma Tau Kok site during the daytime on 28 and 29 September 2021 are as follows: <ul style="list-style-type: none"> - Construction activities on 28 and 29 September 2021 Daytime (i.e. 08:00 – 18:30) <ul style="list-style-type: none"> • Kingpost Installation - According to the Contractor information, piling work for kingpost installation was conducted near the sea wall and hence surface runoff was created. <p>B. Mitigation Measures Undertaken by the Contractor:</p> <ul style="list-style-type: none"> - As a mitigation measure for water quality, the piling work was conducted within the fully enclosed double silt curtain on 28 and 29 September 2021. <p>C. Findings from the joint site inspection with ER, Contractor and ET on 29 September 2021:</p> <ul style="list-style-type: none"> - The regular site inspection was conducted by ER, Contractor and ET at 09:30 on 29 September 2021 (Wednesday), no runoff was observed to be overflowed from Ma Tau Kok site to the marine during the site inspection. <p>D. Conclusion:</p> <ul style="list-style-type: none"> - A complaint regarding effluent discharge was observed on 29 September 2021. As reported by Contractor, the runoff was created by the piling works of kingpost installation. In order to mitigate the effect on water quality, a double silt curtain for the piling works near the sea wall was implemented by the Contractor. 	Closed	0	43

	Date received	Subject	Status	Total no. received in this month	Total no. received since project commencement
		E. Recommendations: The following recommendations are suggested: - Ensure all construction activities to be carried in compliance with the requirements of the Environmental Impact Assessment Ordinance (EIAO). - Conduct the regular visual inspection for the silt curtain to ensure the effectiveness for minimize the impact of the marine water. - The Contractor was recommended to keep track of the surrounding marine water environment.			
Notification of summons	--	--	--	0	0
Successful prosecutions	--	--	--	0	0