Monthly Environmental Monitoring & Auditing Report

Contract No. HY/2014/09 Central Kowloon Route - Ho Man Tin Access Shaft

Location: SKH Tsoi Kung Po Secondary School

Monitoring date: 24 February 2018

 $Parameter: \qquad \qquad L_{eq}, L_{10}, \;\; L_{90}$

Major Site Activities Diaphragm wall construction, decant of structure

Major noise source breaker, nearby traffic

Other Factors NA

Noise Monitoring data:

Date	Weather	Start Time	-	End Time	LAeq	L10	L90
24/2/2018	Sunny	14:30	-	15:00	68.6	76.5	64.8