

Appendix K

Cumulative Statistics on
Exceedances, Complaints,
Notifications of Summons and
Successful Prosecutions

Table K-1 Environmental Complaints Log

Complaint Log No.	Date of Complaint	Received From	Received By	Nature of Complaint	Investigation/Mitigation Action	Status
EC173_CKRCT20230728_698	28 July 2023	The Contractor Hotline	The Contractor & Engineer	Construction Noise and Dust	<p>The resident of Cascades complained about the noise and dust nuisance generated by the breaking works at HMT construction site on 28 July 2023. He/she complained about the noise and dust nuisance generated every Monday to Saturday on 07:00 hours to 19:00 hours was affecting the nearby public. He/she questioned about why the noise enclosure was removed and the completion date of the construction site.</p> <p>According to the information from the Contractor, noise enclosure was demolished because of the foundation works of the ventilation building.</p> <p>According to the information from the Contractor, breaking on surface was conducted at daytime on 28 July 2023 from 07:00 hours – 19:00 hours, no breaking was conducted at nighttime on the same day. This activity was conducted in</p>	Investigation report was finalized on 10 August 2023.

Complaint Log No.	Date of Complaint	Received From	Received By	Nature of Complaint	Investigation/Mitigation Action	Status
					<p>accordance with the requirement set out in the Technical Memorandum of Environmental Impact Assessment Ordinance (EIAO-TM). The mitigation measures including the use of QPME and movable noise barrier at ground surface were implemented following the approved CNMMP (Rev. H).</p> <p>ET conducted construction noise monitoring (Leq (30 min)) at the monitoring location, SKH Tsoi Kung Po Secondary School (M-N3), in July 2023, in accordance with the requirement set out in the EM&A Manual. The noise monitoring results carried out in July 2023 complied with the noise criteria stipulated in EIAO-TM.</p> <p>ET conducted construction dust monitoring (1-hr TSP & 24-hr TSP) at the monitoring location, SKH Tsoi Kung Po Secondary School (M-A3), in July 2023, in accordance with the requirement set out in the EM&A Manual. The dust monitoring results</p>	

Complaint Log No.	Date of Complaint	Received From	Received By	Nature of Complaint	Investigation/Mitigation Action	Status
					<p>carried out in July 2023 complied with the dust criteria stipulated in EIAO-TM.</p> <p>To further minimize the noise and dust impact, the following actions were taken by the Contractor:</p> <p>Additional noise barriers were provided to minimize the noise nuisance.</p> <p>Frequent water spray on the construction site was conducted by the Contractor.</p> <p>The use of QPME and movable noise barrier at ground surface were implemented following the approved CNMMP (Rev. H).</p> <p>In addition, Resident Site Staff (RSS) of the Project will supervise the site work activities and the implementation of noise mitigation measures will be audited by ET and RSS.</p> <p>The Contractor was suggested to maintain good relationship with the</p>	

Complaint Log No.	Date of Complaint	Received From	Received By	Nature of Complaint	Investigation/Mitigation Action	Status
					nearby sensitive receivers/ stakeholders which may be affected by the construction works such as providing better/ more detailed information of the work nature and inform in advance of the noisy works to the nearby residents.	

Table K-2 Cumulative Statistics on Complaints, Notifications of Summons and Successful Prosecutions and Public Engagement Activities

Reporting Period	Complaints	Notifications of Summons and Prosecutions	Public Engagement Activities
This Month	1	0	0
Cumulative Project-to-Date	174	0	0

Table K-3 Cumulative Statistics on Monitoring Exceedance

Monitoring Parameter	Month/Year	No. of Exceedance	
		Action	Limit
1-hour TSP	No. of Exceedance This Month	0	0
	Cumulative Project-to-Date	0	0
24-hour TSP	No. of Exceedance This Month	0	0
	Cumulative Project-to-Date	0	0
Noise (LAeq (30min))	No. of Exceedance This Month	1	0
	Cumulative Project-to-Date	142	0