

Appendix J**Cumulative Statistics on Complaints, Notification of Summons and Successful Prosecutions**

	Date received	Subject	Status	Total no. received in this month	Total no. received since project commencement
Environmental complaints	19 March 2019 (Referred by the Contractor on 19 March 2019)	<p>Environmental Complaint No: EC-008-CKRKTW20190315_01_C013</p> <p><u>Details of Complaint:</u></p> <p>A complaint was received by Environmental Protection Department on 14 and 18 March 2019 (EPD reference: 19-7449 & 19-7732). The complaint was notified by EPD and referred by the Contractor on 19 March 2019 regarding muddy plume caused by marine works of Central Kowloon Route – Kai Tak West, Kowloon on 13 and 18 March 2019.</p> <p><u>Details of Investigation and findings:</u></p> <p>According to the Contractor information, construction works was only conducted within fully-enclosed silt curtain. Muddy plume observed outside the silt curtain could be caused by the movement of transportation boat when berthing to marine platform, given the shallow depth of typhoon shelter.</p> <p>Regular site inspection was conducted by ET and IEC on 20 March 2019, the silt curtain was integral and no muddy plume was observed. Additional silt curtain and proper screening were also deployed near the section of clutch pipe pile driving at inner side.</p> <p>It is considered that the proper mitigation measures for the marine works were provided by the Contractor during the site inspection. The potential source for the muddy plume was caused by the variation of the surrounding water quality. To conclude, this complaint is considered to be not project related.</p>	Closed	2	9
	27 March 2019 (Referred by the Contractor on 29 March 2019)	<p>Environmental Complaint No: EC-009-CKRKTW20190329_01_C014</p> <p><u>Details of Complaint:</u></p> <p>A complaint was received by Highway Department on 27 March 2019 and transferred it to AMMJV on 28 March 2019. The complaint was notified by AMMJV and referred by the Contractor on 29 March 2019 regarding muddy plume observed outside the silt curtain of Central Kowloon Route – Kai Tak West, Kowloon on 27 March 2019.</p> <p><u>Details of Investigation and findings:</u></p> <p>The investigation for the complaint on 27 March 2019 is still in progress and will be reported in the next reporting period.</p>	Ongoing		
Notification of summons	--	--	--	0	0
Successful prosecutions	--	--	--	0	0