

Appendix J

Cumulative Statistics on Complaints, Notification of Summons and Successful Prosecutions

	Date received	Subject	Status	Total no. received in this month	Total no. received since project commencement
Environmental complaints	19 September 2022 (Referred by Gammon Construction Limited on 22/9/2022)	<p>ENVIRONMENTAL COMPLAINT NO.: EC-055</p> <p style="text-align: center;"><u>Details of Complaint</u></p> <p>An environmental complaint (CKRKTW20220919_01_C116) was received and referred by Gammon Construction Limited on 19 and 22 September 2022.</p> <p>The complaint is related to the odour from construction machines described as follows:</p> <p>Date of Complaint received: 19 September 2022</p> <p>Details of Complaint:</p> <p>- "Industrial odour" like the exhaust gas from the engine arose from the CKR construction site near Ma Tau Kok since 15 September 2022. The complainant claim that "the smell is not pungent, but it is very unpleasant".</p> <p>(周太居住單位位於翔龍灣6座高層3X樓，單位分別面向海及巴士站方向，並已於上址住多時。周太指有關「工業異味」有如啟動引擎後排放出的廢氣味道，味道不算刺鼻，但十分難聞。)</p> <p><u>Details of Investigation and findings:</u></p> <p>According to the information provided by the Contractor, 2 excavators, 2 generators and 2 mobile cranes were operated at Ma Tau Kok between 15 to 19 September 2022.</p> <p>As reported by the Contractor, routine maintenance for all machines at the site has been provided by the Contractor to make sure that those machines were well-maintenance before commencing construction works. The fuel filter in the machines will be checked frequently when it has functioned more than 500 hours or six months in accordance with general practice from the Contractor. Maintenances were provided to equipment in the construction site near Ma Tau Kok on 1, 5 and 23 September 2022 to ensure all the equipment operated properly.</p> <p>Besides, Euro V diesel was also used for the machinery fuel to comply with the standard in Cap. 311I Air Pollution Control (Fuel Restriction) Regulations.</p> <p>The regular site inspections were conducted by ET and the Contractor on 14 and 21 September 2022. No malodour was smelled from the machines during the site inspections. In addition, proper NRMM labels were affixed on the operated machines to comply with the requirement in Cap. 311Z Air Pollution Control (Non-road Mobile Machinery) (Emission) Regulation.</p> <p>It is considered that machines have been maintained properly by the Contractor and no unpleasant smell was detected during the site inspections at Ma Tau Kok on 14</p>	The investigation was completed and closed	1	54

	Date received	Subject	Status	Total no. received in this month	Total no. received since project commencement
		and 21 September 2022. <u>Recommendations:</u> The following recommendations are suggested: -Closely monitor the condition of the construction machines before commencing construction works. -Ensure all construction activities to be carried are in compliance with the requirements of the Environmental Impact Assessment Ordinance (EIAO).			
Notification of summons	--	--	--	0	0
Successful prosecutions	--	--	--	0	0